

FAE1 Fume Extractor 415-FAE1-2B

FAE1

Fume Extractor for 1 Workbench

The FAE is **the most effective solution to avoid exposure to solder fumes**. The extractor activates and operates only when soldering.

The extractor starts up only when soldering. This function not only saves power, but also extends the life span of the equipment, including the filter.

The FAE1 stand has an **integrated vacuum system** that detects when the tool is at rest and automatically **absorbs excess fumes**.

The FAE1 provides direct **connection of up to 4 soldering or rework stations** and an additional **4 fume extraction stands**.

It can be controlled via JBC Stations, a pedal, a robotic system or a PC.

It has 3 predefined levels of aspiration: low, medium and high. It also features a custom mode where the airflow can be set within the lowest (10%) and maximum rates (100%).



ABOUT KAISERTECH

Founded in 1998, Kaisertech Ltd is situated in Eastleigh, Hampshire.

Through hard work and dedication Kaisertech has grown to be a well-recognized supplier of electronic production equipment and tools.

Specialists in: Soldering, Static Control, Vision, Industrial Furniture, Electric Screw Drivers & Special Projects.

FAE1 Fume Extractor 415-FAE1-2B

Basic working system

Flexible arm Ø50 mm (Ref. FAE020 or FAE070)

Ref. **FAE020**
Completely flexible arm to be adjusted to your workbench (hole drilling required). Length: 0,94 m - 37 in (compressed).

Ref. **FAE070**
Flexible arm + clamp to fix it to the table. Length: 0,94 m - 37 in (compressed).

Flexible Hose Ø50 mm

Ref. **FAE010**
Connect the Fume Extractor to Flexible Arm. Length: 1,5 m - 59 in (unfolded).

Stand Aspiration Ducts (Ref. FAE050 or FAE060)

Ref. **FAE050**
Fume Inlet Duct for Modular Stands. Length: 106 mm (4.17 in).



Ref. **FAE060**
Fume Inlet Duct for Compact stations. Length: 106 mm (4.17 in).



Accessory for Stand Aspiration (Ref. FAE030 or FAE040)

Ref. **FAE030**
Accessory for stand aspiration. Connect up to 4 stands (hole drilling required).

Ref. **FAE040**
Accessory for stand aspiration (up to 4 stands) + clamp to fix it to the table.


For a **basic working system** you need:

1 Flexible arms Ø50
Ref. **FAE070** or Ref. **FAE020**


2 Flexible Hoses Ø50
Ref. **FAE010**

1 Accessory for Stand Aspiration
Ref. **FAE030** or Ref. **FAE040**

Stand Aspiration Ducts (one per tool, up to 4 units)
Ref. **FAE050** or Ref. **FAE060**



Main screen
for 1 work intakes



ABOUT KAISERTECH

Founded in 1998, Kaisertech Ltd is situated in Eastleigh, Hampshire.

Through hard work and dedication Kaisertech has grown to be a well-recognized supplier of electronic production equipment and tools.

Specialists in: Soldering, Static Control, Vision, Industrial Furniture, Electric Screw Drivers & Special Projects.

FAE1 Fume Extractor 415-FAE1-2B**2 work intakes configuration assembly
(optional configuration)****Flexible arm Ø50 mm**
(Ref. FAE020 or FAE070)Ref. **FAE020**

To be assembled directly on your workbench (hole drilling required)

Ref. **FAE070**

Length: 1 m (39.37 in)

To be assembled on your workbench with the included clamp

Flexible Hose Ø50 mmRef. **FAE010**Length: 1,5 m
(59.05 in)

Connect the Fume Extractor to the flexible arm.




In this configuration aspiration at stand is not available. Note that in this configuration, suction force per intake is decreased when compared to 1 work intake configuration. Change Work intakes parameter into 2 in order to set this configuration.

For 2 work intakes configuration assembly you need:

2 Flexible arms Ø50
Ref. **FAE070** or Ref. **FAE020**

2 Flexible Hoses Ø50
Ref. **FAE010**

Main screen
for 2 work intakes

**ABOUT KAISERTECH**

Founded in 1998, Kaisertech Ltd is situated in Eastleigh, Hampshire.

Through hard work and dedication Kaisertech has grown to be a well-recognized supplier of electronic production equipment and tools.

Specialists in: Soldering, Static Control, Vision, Industrial Furniture, Electric Screw Drivers & Special Projects.