

Automatic Solder Feeder

Model references: SF

Error num.	Displayed message	Solution
1	WARNING #1 Check if the tin is loaded. If it is, contact with JBC. If it isn't, execute the "Tin Reload Process" in Main Menu	Add tin wire with the function "Tin Reload Process" from the main menu. Undo the obstruction. If not solved, contact with the Technical Service.