


SF-210VA 230V
SF-110VA 100/120V
AUTOMATIC SOLDER FEEDER



SPARE PARTS		
SF-2A / SF-1A:		
- CIRCUITS:		
- SF-2A		0018240
- SF-1A		0018744
- ENCLOSURE		
- TOP		0018021
- BOTTOM		0018019
- FRONT		0018020
- BACK		0018022
- LATERAL		0018023
- BLADE (x5)		0018635

SF-210VA 230V FUSE T-0,1A
SF-110VA 100/120V FUSE T-0,2A